Notice

SANYO

☐ CORRECTION ● PRODUCTION CHANGE
☐ SERVICE FLASH ☐ ADD INFORMATION

FILE NO.

REVISION 0

Please add this notice to the Service Manual listed below.

Category: **COLOR TELEVISION** Date: **JULY / 12 / 2011**

Model: **DP26640** Effective from : Chassis No. **P26640-08**

Destination: **U.S.A. / CANADA** REF : **No. SM780181-08**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's,** additional Service Literature is required. This chassis is similar to Chassis No. P26640-06. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P26640-06 used in Model DP26640 (SM780182).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be changed from **03h** to **04h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A : Misprint B : Quality Reliability C : Standardization
D : Design E : Add as a possible sub F : Schematic location change
G : Purchasing Request

© Sanyo Manufacturing Corporation 2011

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange-ability	Reason
Page 18, Chassis Electrical Parts List	A200	Old	1AA0B10N306A0	ASSY,PWB,ANALOG-COMP-N8MK	1	NO	D
		New	1AA0B10N30600	ASSY,PWB,ANALOG-COMP-N8LK	1	NO	
	⚠EL901	Old	1AV4T40C17000	LCD(M260TWR1 R1)	1	NO	D
		New	1AV4T40C27000	LCD(T260XW04 V7)	1	NO	
	⚠WK5LV –PN	Old	1AA4W30B66500	LVDS CABLE,40P-31P	1	NO	D
		New	K1PY40Y00013	CORD, 30P-40P(LVDS)	1	NO	

For detailed panel (EL902) service differences refer to the following.

P26640-06 (OLD)

Part Number	**Description**
⚠ 1AV4U20C46200	UNIT,INVERTER

P26640-08 (NEW)

Part Number	**Description**
⚠ 819.26T05.005	INVERTER 4T40C27000,T260XW04

© Sanyo Manufacturing Corporation 2011

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000

July, 2011 SMC

Published in Mexico

DP26640, N8MR, PRODUCT CODE 113023504

REFERENCE No. SM780181-08